

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**


[FIG. 1]




000000-000000



[FIG. 3]



[FIG. 4]



✓


[illegible]

Fig. 6(a)





Fig. 6(b)










Fig. 10 is a perspective view of a light emitting device 50. The device includes a substrate 9a, a light emitting layer 16, and a light reflecting layer 301. A light emitting element 50a is shown emitting light at an angle  $\theta$ .








[FIG. 9]



[FIG. 10]



五


[illegible]

Fig. 12(a)




Fig. 12(b)







Fig. 12(c)




[FIG. 13]




[FIG. 14]



[FIG. 15]



[FIG. 16]



[FIG. 17]

